

UPC-A convert into EAN-13

Step 1: Scan the bar code 'Enable setting', let scanner can decode configuration bar code.



Enable setting

Step 2: Scan the bar code 'Enable UPC-A' to enable scanner decode UPC-A.



Enable UPC-A

Step 3: Scan bar code 'UPC-A convert into EAN-13'.



UPC-A convert into EAN-13